

Keep your aerosol products clean

After you have completed your work, turn the can upside down and depress the tip for a few seconds until only vapor appears.

This will clean the spray head and dip tube.

Wipe off all overspray from the head before you put the can away.

Clogged sprayheads can be removed and soaked in a lacquer thinner.

Inserting a fine needle into the orifice of the head will help clean clogged sprayheads.